



ASTRUSTEE FOR THE U.F.I. UNIT TRUST A.C.N. 081 671 436

479 Great Eastern Highway, Redcliffe WA 6104. PO Box 141 Guildford WA 6935.
Telephone: Service (61 8) 9479 7400. Accounts (61 8) 9479 7059. Facsimile (61 8) 9479 7401
www.unitedfuel.com.au

31st January 2006

Major Auto Technics
6 Elgee Street
Bellevue WA 6056

RE: CONDITION REPORT INJECTION PUMP
TOYOTA HILUX - REGISTRATION NUMBER VC1202

Dear Sir

The above vehicle was fitted with a Fuelstar combustion catalyst during July 2004 and has subsequently traveled approximately 30,000 Kilometers since fitment. During recent engine maintenance it was decided to remove and service the injection pump. The pump was dismantled and inspected for wear and tear, it was found to be in an excellent state of repair. Internal components were clean with minimal wear found in areas that are traditionally known to be wearing on high mileage injection pumps such as this one.

We have no doubt that the fuelstar has and will contribute to an extended product life for the injection pump on this vehicle. We are satisfied that the product meets the claims of the manufacturer. Thank you for introducing the product to us.

Yours sincerely

Ken Ringrose – Director
Service Manager
Light Commercial Division